



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

05/04/2006

Supervisor 10071

Mine Name: ML 47821&46956/Cubical2

**Operator Name:**

Sprunger's Minerals  
Mike & Sandra Spunger  
PO Box 38054

Leamington, Ut 84638

**Inspector(s):** Tom Munson

**Other Participants:** None

**Mine Status:** active

**Permit number:** S230057

**Inspection Date:** 05/04/2006

**Time:** 3 PM

**Weather:** Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Perform an Annual inspection

**Directions to Site:**

West side of the Thomas Range, west of Delta

**Inspection Summary:**

The site has approximately one acre of disturbance and a backhoe sits onsite.

**Conclusions and Recommendations:**

The site be inspected annually to update disturbance as it appears to be active.

**Inspector's Signature**

Thomas Munson

**Date:**

10/30/06

tm:jb

cc:

Operator

Attachment: Photos

O:\M023-Juab\S0230057-Sprunger-3sites\Inspections\insp-05042006.doc



S/023/057 ML 47821



8/04/06



SITLA LEASE ML 47821



5/04/06



SIT LA LEASE ML47821 S/023/057



S/04/06



S/023/057 ML 47821



5/04/06



S/023/057 ML 47821



S/04/06